Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2208673	Town Pump Inc Boulder	703 N Main	Boulder	59632	(406) 225-4330

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 04 Currently in Use	4477	1/1/1989 17 / No	Diesel 12,000	STI-P3 Impressed Current	Flexible Plastic Secondary Containment	Pressurized	<pre>ABC●EFGHIJKL ● ●EFGHIJKL</pre>	Yes Yes Yes Yes
2 / 05 Currently in Use	4478	5/10/1989 17 / No	Diesel 9,000	STI-P3 Impressed Current	Flexible Plastic None	Pressurized	(ABCOEFGH))(CL	Yes Yes Yes Yes
3 / 02 Currently in Use	2486	5/10/1977 29 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic Secondary Containment	Pressurized	(ABCOEFGH)(KL (O) (E) (B) (H)(KL)	Yes Yes Yes Yes
4 / 03 Currently in Use	2487	5/10/1977 29 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic Secondary Containment	Pressurized	(ABCOEFGH) (KL (O) (EFGH) (KL)	Yes Yes Yes Yes
5 / 01 Currently in Use	2485	5/10/1977 29 / No	Gasoline 12,000	Impressed Current	Fiberglass Reinforced Plastic Secondary Containment	Pressurized	(ABCOEFGH) (KL) (O O EFGH) (KL)	Yes Yes Yes Yes
6 / 06 Currently In Use	4479	4/1/2001 05 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B OEFOHIJKL	Yes Yes Yes Yes
7 / 07 Currently In Use	4480	4/1/2001 05 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B OEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 1 of 10

Owner Name and Address: Harlows School Bus Service Inc PO Box 399 Rolette ND 58366 Phone: (800) 437-2072

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2212378	Harlows School Bus Service Inc Boulder	101 N Main St	Boulder	59632	(406) 225-3344

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
6 / 06 Currently in Use	2710	10/1/1991 14 / No	Gasoline 2,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<pre>A • C • E F G H I J K L • D E F G H I • K L</pre>	Yes Yes Yes Yes
7 / 07 Currently in Use	2711	10/1/1991 14 / No	Diesel 2,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<pre></pre>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 2 of 10

Owner Name and Address: Kip Huckaba 770 Mt Highway 2 E Cardwell MT 59721 Phone: (406) 287-5092

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2213424	Cardwell Store LLC	770 US Highway 2 E	Cardwell	59721	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3193	4/1/1994 12 / No	Gasoline 9,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	\(\ 8 \cents \ \ \ \cents \ \ \cents \ \ \cents \cents \ \cents \cents \ \cen	Yes Yes Yes Yes
2 / 02 Currently in Use	3194	4/1/1994 12 / No	Gasoline 3,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL (D) (D) (E) (B) (D) (B) (D) (D) (D) (D) (D) (D) (D) (D) (D) (D	Yes Yes Yes Yes
3 / 03 Currently in Use	3195	4/1/1994 12 / No	Diesel 6,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	ABC●EFGHIJ®L ● ●EFGHIJ®L	Yes Yes Yes Yes
4 / 04 Currently in Use	3196	4/1/1994 12 / No	Diesel 6,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	ABC • E F G H J K L • • E F G H J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 10

Owner Name and Address: Montana City Store LLC 1 Jackson Creek Road Clancy MT 59634 Phone: (406) 442-6625

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
2201822	Montana City Store LLC	1 Jackson Creek Road	 Clancy	59634	(406) 442-6625	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
5 / 05 Currently in Use	1668	7/1/1988 18 / No	Diesel 4,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B (DEFOHIJKL	Yes Yes Yes Yes
6 / 06 Currently in Use	1669	7/1/1988 18 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	B DEF GH] J & L	Yes Yes Yes Yes
7 / 07 Currently in Use	1670	7/1/1988 18 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGH) (KL B (DEFOH) (KL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 4 of 10

Owner Name and Address: EMMK LLC 3655 US Highway 12 E Helena MT 59601 Phone: (406) 442-4804

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2202898	Clancy Store UST	10 E Clancy St	Clancy	59634	(406) 933-8278

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	3534	4/26/1984 22 / No	Gasoline 2,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Safe Suction	DEFGHJ&L	Yes Yes Yes Yes
3 / 03 Currently in Use	4647	4/10/1993 13 / No	Gasoline 1,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Safe Suction	DEFGHJ&L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 5 of 10

Owner Name and Address: Ash Grove Cement West Inc 100 MT Highway 518 Clancy MT 59634 Phone: (406) 442-8855

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
2202928	Ash Grove Cement West Inc	100 MT Highway 518	Clancy	59634	(406) 442-8855	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently in Use	392	3/30/1990 16 / No	Gasoline 4,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized		Yes Yes Yes Yes
5 / 05 Currently in Use	393	3/30/1990 16 / No	Diesel 4,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	ABC®EF®H 1 3%L ● ®EF®H 1 3%L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 6 of 10

Owner Name and Address: Sutey Oil Co Inc 2000 Holmes Ave Butte MT 59701 Phone: (406) 494-2305

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2200980	The Corner Store Whitehall	203 W Legion Ave	Whitehall	59759	(406) 287-3746

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 06 Currently in Use	529	10/15/1993 12 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL OEFGHIJKL	Yes Yes Yes Yes
2 / 04 Currently in Use	527	10/15/1993 12 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGH() (KL)	Yes Yes Yes Yes
3 / 05 Currently in Use	528	10/15/1993 12 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EF@H①&L ● EF@H①ØL</pre>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 7 of 10

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location Ci	ty Zip	Location Phone	
2203645	Town Pump Inc Whitehall	415 N Whitehall St	Whitehall	59759	(406) 287-5630	_

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	2476	1/1/1968 38 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	2477	1/1/1968 38 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH))(C) (D) (E) (F) (H) (J) (C)	Yes Yes Yes Yes
3 / 03 Currently in Use	2478	1/1/1978 28 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH))(KL) (O) (E) F(G) H) (J) (KL)	Yes Yes Yes Yes
4 / 04 Currently in Use	2479	1/1/1976 30 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH))(KL) (O) (E) F(G) H) () (K)	Yes Yes Yes Yes
5 / 05 Currently in Use	2480	1/1/1978 28 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	ABC•EFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
6 / 06 Currently in Use	2481	1/1/1978 28 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
7 / 07 Currently in Use	2482	1/1/1986 20 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABCOEFGHIJ&L</pre>	Yes Yes Yes Yes
8 / 08 Currently in Use	2483	1/1/1987 19 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(A) B C (E) F (G) H (1) (R) (L)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

9 / 09	2484 1/1/1987	Diesel	STI-P3	Flexible Plastic	Pressurized	(ABCOEFGH))(V)	Yes
Currently in Use	19 / No	12,000	None	Double-Walled		(DEFGH))(V)	Yes Yes Yes
10 / 10 Currently In Use	4198 5/1/2000 06 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized		Yes Yes Yes Yes
11 / 11	4199 5/1/2000	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	ABC • E F • H 1 J % L	Yes
Currently In Use	06 / No	10,000	Double-Walled	Double-Walled		B • E F • H 1 J % L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006

Owner Name and Address: Golden Sunlight Mines Inc 453 MT Highway 2 E Whitehall MT 59759 Phone: (406) 287-3257

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	'
2204689	Golden Sunlight Mines Inc UST	453 MT Highway 2 E	 Whitehall	59759	(406) 287-3257	

TankiD/Alt TankiD Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Temporarily Out of Use		4/19/1983 23 / No	Other 3,000	Asphalt Coated or Bare Steel None	Bare Steel None	Pressurized (B DEFGHIJK•	Yes No No No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 10 of 10